

Triumph Actuation Systems - Yakima
Current Service Bulletin List

| Service Bulletin No. | Revision | Part No. | Nomenclature | CMM No | Rev Date |
|----------------------|----------|----------|---|----------|------------|
| 17008-32-1 | 1 | 17008 | Main Landing Gear Side Stay Actuator Install New Cap Screws | 32-30-29 | 3/23/1993 |
| 17008-32-2 | - | 17009 | CL601-RJ Main Landing Gear Side Stay Actuator Retract Port Housing Replacement | 32-30-29 | 11/29/1993 |
| 17008-32-3 | 2 | 17010 | CL601-RJ Main Landing Gear Side Stay Actuator Lock and Lock Spring Refreshments | 32-30-29 | 6/22/1995 |
| 17008-32-4 | - | 17011 | CL601-RJ MLG Side Stay Actuator Assembly Replacement of the Retract Port Housing Cap Screws | 32-30-29 | 2/28/1995 |
| 17008-32-5 | 1 | 17012 | CL601-RJ Main Landing Gear Side Stay Actuator Lock Indicator Pin | 32-30-29 | 3/14/1996 |
| 17008-32-6 | 1 | 17013 | CL601-RJ Replacement of the Side Stay Actuator Assembly | 32-30-29 | 9/22/2003 |
| 17008-32-7 | - | 17014 | CL601-RJ MLG Side Stay Actuator Assembly Visually Inspect the Rod End to Confirm Sealing and Torque Integrity | 32-30-29 | 4/30/2002 |
| 19011-32-1 | 4 | 19011 | MLG Side Stay Actuator Assembly Triumph P/N 19011-103, 19011-105 Spherical Bearing Replacement | 32-30-30 | 5/7/2018 |
| 40310-32-1 | - | 40310 | Landing Gear MLG Side Brace Actuator Assembly Modification to Correct Internal Part Traceability GE Aviation Part No. 40310-103 | 32-30-43 | 11/16/2011 |
| 40310-32-2 | - | 40310 | Landing Gear MLG Side Brace Actuator Assembly Triumph P/N 40310-103 Split Ball Bearing Replacement | 32-30-43 | 7/26/2017 |
| 2-7457-32-116 | NC | 2-7457 | Hydraulics - Main Landing Gear Door Actuator Assembly: Push Rod Replacement | 32-12-01 | 8/15/2001 |
| 2-7460-32-106 | 3 | 2-7460 | Hydraulics- Anti-Skid Shuttle Valve Module: Modification to eliminate undesirable fluid transfer | 32-42-01 | 7/12/2001 |
| 2-7680-27-1 | 1 | 2-7680 | Flow Rate Fuse Assembly | 27-32-02 | 11/4/2011 |
| 2-7857-32-1 | 1 | 2-7857 | Landing Gear- Nose Landing Gear Actuator Assembly- Extend Snubber Ring Replacement | 32-34-01 | 12/15/2017 |
| 2-7857-32-2 | - | 2-7857 | Landing Gear- Nose Landing Gear Actuator Assembly- Split Ball Bearing Replacement | 32-34-01 | 5/5/2017 |
| 2-7897-32-100 | 1 | 2-7897 | Quantity Measuring Fuse Assembly | 32-32-01 | 1/16/2006 |

Triumph Actuation Systems - Yakima
Current Service Bulletin List

| Service Bulletin No. | Revision | Part No. | Nomenclature | CMM No | Rev Date |
|----------------------|----------|-----------------|--|----------|------------|
| 2-7897-32-101 | - | 2-7897 | Fuse Assembly - Quantity Measuring Torque Value Clarification | 32-32-01 | 5/10/2010 |
| 2-7897-32-102 | 5 | 2-7897 | Landing Gear Fuse Assembly - Hydraulic Quantity Measuring Fuse Housing Failure | 32-32-01 | 3/11/2014 |
| 2-8020-32-100 | - | 2-8020 | Hydraulics - Fuse, Auto Quantity Measuring Self Resetting: Replacement | 32-31-04 | 6/25/2007 |
| 2-8292-32-1 | - | 2-8292 | Landing Gear NLG Retract Actuator Assembly Triumph P/N 2-8292-3 Re-application of HVOF Coating | 32-34-05 | 1/5/2017 |
| 2-8294-32-1 | - | 2-8294 | Nose Landing Gear Door Actuator Triumph P/N 2-8294-1 High Stroking Friction | 32-34-07 | 9/30/2016 |
| 2-8294-32-2 | B | 2-8294 | Landing Gear NLG Door Actuator Assembly Triumph P/N 2-8294-1, and -3 Split Ball Bearing Replacement | 32-34-07 | 4/25/2018 |
| 2-8294-32-3 | - | 2-8294 | Landing Gear: Nose Landing Gear Door Actuator Triumph P/N 2-8294-1/-3 Cylinder Assembly Replacement | 32-34-07 | 5/12/2017 |
| 2-8295-32-1 | A | 2-8295 | Landing Gear MLG Retract Actuator Assembly Triumph P/N 2-8295-8 Re-application of HVOF Coating | 32-32-10 | 2/24/2017 |
| 2-8297-32-1 | - | 2-8297 | Landing Gear Main Landing Gear Drag Brace Actuator | 32-32-12 | 3/16/2016 |
| 2-8298-32-1 | - | 2-8298 | Landing Gear Main Landing Gear Door Actuator Assembly | 32-32-13 | 5/30/2014 |
| 2-8299-32-1 | 1 | 2-8299 | Landing Gear Main Landing Gear Truck Position Actuator Assembly | 32-32-14 | 11/26/2013 |
| 2-8299-32-2 | B | 2-8299 | Landing Gear MLG Truck Position Actuator Assembly Triumph P/N 2-8299-2 Split Ball Bearing Replacement | 32-32-14 | 4/25/2018 |
| 2-8300-32-001 | 0 | 2-8300 | Landing Gear Nose Wheel Steering Valve Module- Conversion of 2-8300-4 or 2-8300-5 to 2-8300-6 | 32-51-01 | 7/8/2013 |
| 2-8301-32-1 | - | 2-8301 | Landing Gear Nose Wheel Steering Commutator | 32-51-02 | 12/14/2015 |
| 2-8302-32-1 | - | 2-8302 / 2-8320 | Landing Gear Nose Wheel Steering Commutator Valve L, R | 32-51-03 | 11/13/2013 |
| 2-8311-32-001 | - | 2-8311 | Replacement of Incorrect Label Identifying Unit 2-8311-1 with Label Correctly Identifying Unit as 2-8311-2 | 32-35-03 | 5/15/2014 |

Triumph Actuation Systems - Yakima
Current Service Bulletin List

| Service Bulletin No. | Revision | Part No. | Nomenclature | CMM No | Rev Date |
|----------------------|----------|----------------|---|----------|-----------|
| 2-8314-32-001 | - | 2-8314 | Landing Gear MLG Control Valve Triumph P/N 2-8314-2 Diode Connector Assembly Replacement | 32-32-07 | 3/1/2018 |
| 2-8317-32-001 | - | 2-8317 | Landing Gear MLG Uplock Mechanism (L) Triumph P/N 2-8317-2 | 32-32-09 | 8/17/2016 |
| 2-8318-32-001 | - | 2-8317 | Landing Gear MLG Uplock Mechanism (R) Triumph P/N 2-8318-2 | 32-32-09 | 9/21/2016 |
| 2-8325-32-004 | 0 | 2-8325 | Main Landing Gear Door Uplock Mechanism- Conversion of 2-8325-4 to 2-8325-5 | 32-32-05 | 8/10/2012 |
| 2-8325-32-008 | 0 | 2-8325-50, -51 | Landing Gear- Left Main Landing Gear Door Uplock Mechanism- Conversion of 2-8325-50 to 2-8325-51 | 32-32-77 | 8/10/2012 |
| 2-8326-32-005 | 0 | 2-8326 | Main Landing Gear Door Uplock Mechanism- Conversion of 2-8326-4 to 2-8326-5 | 32-32-05 | 8/10/2012 |
| 2-8326-32-009 | 0 | 2-8326-50, -51 | Landing Gear- Right Main Landing Gear Door Uplock Mechanism- Conversion of 2-8326-50 to 2-8326-51 | 32-32-77 | 8/10/2012 |
| 2-8329-32-001 | 2 | 2-8329 | Landing Gear Nose Landing Gear Control Valve Triumph P/N 2-8329-2 Connector Block Replacement | 32-34-03 | 1/26/2018 |
| 2-8362-32-006 | 0 | 2-8362 | Main Landing Gear Door Uplock Delivery Assembly- Conversion of 2-8362-4 to 2-8362-5 | 32-32-68 | 8/10/2012 |
| 2-8362-32-010 | 0 | 2-8362-50, -51 | Landing Gear- Left Main Landing Gear Uplock Delivery Assembly- Conversion of 2-8362-50 to 2-8362-51 | 32-32-78 | 8/10/2012 |
| 2-8363-32-007 | 0 | 2-8363 | Main Landign Gear Door Uplock Delivery Assembly- Conversion of 2-8363-4 to 2-8363-5 | 32-32-68 | 8/10/2012 |
| 2-8363-32-011 | 0 | 2-8363-50, -51 | Landing Gear- Right Main Landing Gear Door Uplock Delivery Assembly- Conversion of 2-8363-50 to 2-8363-51 | 32-32-78 | 8/10/2012 |
| 2-8474-32-1 | - | 2-8474 | Landing Gear Main Landing Gear Door Actuator Assembly | 32-32-15 | 5/30/2014 |
| 2-8476-32-1 | - | 2-8476 | Landing Gear MLG Retract Actuator Assembly Triumph P/N 2-8476-1 Re-application of HVOF Coating | 32-32-16 | 1/5/2017 |
| 2-8512-32-001 | - | 2-8512 | Landing Gear MLG Uplock Mechanism (L) Triumph P/N 2-8512-1 | 32-32-80 | 9/21/2016 |
| 2-8513-32-001 | - | 2-8513 | Landing Gear MLG Uplock Mechanism (R) Triumph P/N 2-8513-1 | 32-32-80 | 9/21/2016 |

Triumph Actuation Systems - Yakima
Current Service Bulletin List

| <u>Service Bulletin No.</u> | <u>Revision</u> | <u>Part No.</u> | <u>Nomenclature</u> | <u>CMM No</u> | <u>Rev Date</u> |
|-----------------------------|-----------------|-----------------|--|---------------|-----------------|
| 2-8554-32-1 | - | 2-8554 | Landing Gear MLG Side Brace Actuator Assembly Triumph P/N 2-8554-2 Split Ball Bearing Replacement | 32-31-07 | 7/26/2017 |
| 6-0419-32-001 | - | 6-0419 | Hydraulic Alternate Extend Power Pack | 32-35-08 | 10/13/2015 |
| H10411003-32-1 | - | H10411003 | Landing Gear Body Landing Gear Center Door Actuator Assembly | 32-32-55 | 11/29/2012 |
| H10415003-32-1 | - | H10415003 | Outer Door Actuator Assembly - Body Landing Gear, Bonding Strap Upgrade | 32-32-57 | 5/21/2010 |
| H10671-32-001 | 1 | H10671003 | JUN 19/13 Landing Gear- Truck Position Valve- Conversion of H10671003 to H10671004 | 32-32-24 | 7/2/2013 |