

Triumph Actuation Systems - Yakima  
Current Service Letter List

<u>Service Letter No.</u>	<u>Revision</u>	<u>PartNo</u>	<u>Nomenclature</u>	<u>CMM No.</u>	<u>Rev Date</u>
SIL-2-7457-001	-	2-7457	GE Aviation Service Information Letter	32-12-01	2/4/2010
SIL-32-10	-	6-0419	Helicoil Substitutions	32-31-57	8/9/2012
SIL-32-11		2-8343, 2-8344, 2-8345, 2-8346, 2-8347, 2-8353, 2-8354, 2-8355, 2-8356, 2-8379, 2-8464	Transfer of Ownership of Landing Gear Components from Triumph Actuation Systems- Yakima LLC, to the Boeing Company	32-31-45 32-31-47 32-31-48 32-31-49 32-31-50 32-31-47 32-31-48 32-31-50 32-31-45 32-31-56 32-31-51	Contact Boeing for latest revision
SIL-32-2		6-0451, 6-0452, 6-0453, 6-0454	Transfer of Ownership of Landing Gear Components from GE Aviation Systems, to Eaton Aerospace	32-35-14 32-32-21 32-32-22 32-32-23	Contact Eaton Aerospace for latest revision
SIL-32-3	-	2-8020	Boeing Service Bulletin	32-31-04	9/23/2008
SIL-32-7	1	2-8041	Ant- Skid Volumetric Fuse Assembly	32-40-18	3/16/2011