

Triumph Actuation Systems - Yakima
Current Service Bulletin List

Service Bulletin No.	Revision	Part No.	Nomenclature	CMM No	Rev Date
17008-32-1	1	17008	Main Landing Gear Side Stay Actuator Install New Cap Screws	32-30-29	3/23/1993
17008-32-2	-	17009	CL601-RJ Main Landing Gear Side Stay Actuator Retract Port Housing Replacement	32-30-29	11/29/1993
17008-32-3	2	17010	CL601-RJ Main Landing Gear Side Stay Actuator Lock and Lock Spring Refreshments	32-30-29	6/22/1995
17008-32-4	-	17011	CL601-RJ MLG Side Stay Actuator Assembly Replacement of the Retract Port Housing Cap Screws	32-30-29	2/28/1995
17008-32-5	1	17012	CL601-RJ Main Landing Gear Side Stay Actuator Lock Indicator Pin	32-30-29	3/14/1996
17008-32-6	1	17013	CL601-RJ Replacement of the Side Stay Actuator Assembly	32-30-29	9/22/2003
17008-32-7	-	17014	CL601-RJ MLG Side Stay Actuator Assembly Visually Inspect the Rod End to Confirm Sealing and Torque Integrity	32-30-29	4/30/2002
19011-32-1	4	19011	MLG Side Stay Actuator Assembly Triumph P/N 19011-103, 19011-105 Spherical Bearing Replacement	32-30-30	5/7/2018
40310-32-1	-	40310	Landing Gear MLG Side Brace Actuator Assembly Modification to Correct Internal Part Traceability GE Aviation Part No. 40310-103	32-30-43	11/16/2011
40310-32-2	-	40310	Landing Gear MLG Side Brace Actuator Assembly Triumph P/N 40310-103 Split Ball Bearing Replacement	32-30-43	7/26/2017
2-7457-32-116	NC	2-7457	Hydraulics - Main Landing Gear Door Actuator Assembly: Push Rod Replacement	32-12-01	8/15/2001
2-7460-32-106	3	2-7460	Hydraulics- Anti-Skid Shuttle Valve Module: Modification to eliminate undesirable fluid transfer	32-42-01	7/12/2001
2-7680-27-1	1	2-7680	Flow Rate Fuse Assembly	27-32-02	11/4/2011
2-7857-32-1	1	2-7857	Landing Gear- Nose Landing Gear Actuator Assembly- Extend Snubber Ring Replacement	32-34-01	12/15/2017
2-7857-32-2	-	2-7857	Landing Gear- Nose Landing Gear Actuator Assembly- Split Ball Bearing Replacement	32-34-01	5/5/2017
2-7897-32-100	1	2-7897	Quantity Measuring Fuse Assembly	32-32-01	1/16/2006

Triumph Actuation Systems - Yakima
Current Service Bulletin List

Service Bulletin No.	Revision	Part No.	Nomenclature	CMM No	Rev Date
2-7897-32-101	-	2-7897	Fuse Assembly - Quantity Measuring Torque Value Clarification	32-32-01	5/10/2010
2-7897-32-102	5	2-7897	Landing Gear Fuse Assembly - Hydraulic Quantity Measuring Fuse Housing Failure	32-32-01	3/11/2014
2-8020-32-100	-	2-8020	Hydraulics - Fuse, Auto Quantity Measuring Self Resetting: Replacement	32-31-04	6/25/2007
2-8292-32-1	-	2-8292	Landing Gear NLG Retract Actuator Assembly Triumph P/N 2-8292-3 Re-application of HVOF Coating	32-34-05	1/5/2017
2-8294-32-1	-	2-8294	Nose Landing Gear Door Actuator Triumph P/N 2-8294-1 High Stroking Friction	32-34-07	9/30/2016
2-8294-32-2	B	2-8294	Landing Gear NLG Door Actuator Assembly Triumph P/N 2-8294-1, and -3 Split Ball Bearing Replacement	32-34-07	4/25/2018
2-8294-32-3	-	2-8294	Landing Gear: Nose Landing Gear Door Actuator Triumph P/N 2-8294-1/-3 Cylinder Assembly Replacement	32-34-07	5/12/2017
2-8295-32-1	A	2-8295	Landing Gear MLG Retract Actuator Assembly Triumph P/N 2-8295-8 Re-application of HVOF Coating	32-32-10	2/24/2017
2-8297-32-1	-	2-8297	Landing Gear Main Landing Gear Drag Brace Actuator	32-32-12	3/16/2016
2-8298-32-1	-	2-8298	Landing Gear Main Landing Gear Door Actuator Assembly	32-32-13	5/30/2014
2-8299-32-1	1	2-8299	Landing Gear Main Landing Gear Truck Position Actuator Assembly	32-32-14	11/26/2013
2-8299-32-2	B	2-8299	Landing Gear MLG Truck Position Actuator Assembly Triumph P/N 2-8299-2 Split Ball Bearing Replacement	32-32-14	4/25/2018
2-8300-32-001	0	2-8300	Landing Gear Nose Wheel Steering Valve Module- Conversion of 2-8300-4 or 2-8300-5 to 2-8300-6	32-51-01	7/8/2013
2-8301-32-1	-	2-8301	Landing Gear Nose Wheel Steering Commutator	32-51-02	12/14/2015
2-8302-32-1	-	2-8302 / 2-8320	Landing Gear Nose Wheel Steering Commutator Valve L, R	32-51-03	11/13/2013
2-8311-32-001	-	2-8311	Replacement of Incorrect Label Identifying Unit 2-8311-1 with Label Correctly Identifying Unit as 2-8311-2	32-35-03	5/15/2014

Triumph Actuation Systems - Yakima
Current Service Bulletin List

Service Bulletin No.	Revision	Part No.	Nomenclature	CMM No	Rev Date
2-8314-32-001	-	2-8314	Landing Gear MLG Control Valve Triumph P/N 2-8314-2 Diode Connector Assembly Replacement	32-32-07	3/1/2018
2-8317-32-001	-	2-8317	Landing Gear MLG Uplock Mechanism (L) Triumph P/N 2-8317-2	32-32-09	8/17/2016
2-8318-32-001	-	2-8317	Landing Gear MLG Uplock Mechanism (R) Triumph P/N 2-8318-2	32-32-09	9/21/2016
2-8325-32-004	0	2-8325	Main Landing Gear Door Uplock Mechanism- Conversion of 2-8325-4 to 2-8325-5	32-32-05	8/10/2012
2-8325-32-008	0	2-8325-50, -51	Landing Gear- Left Main Landing Gear Door Uplock Mechanism- Conversion of 2-8325-50 to 2-8325-51	32-32-77	8/10/2012
2-8326-32-005	0	2-8326	Main Landing Gear Door Uplock Mechanism- Conversion of 2-8326-4 to 2-8326-5	32-32-05	8/10/2012
2-8326-32-009	0	2-8326-50, -51	Landing Gear- Right Main Landing Gear Door Uplock Mechanism- Conversion of 2-8326-50 to 2-8326-51	32-32-77	8/10/2012
2-8329-32-001	2	2-8329	Landing Gear Nose Landing Gear Control Valve Triumph P/N 2-8329-2 Connector Block Replacement	32-34-03	1/26/2018
2-8362-32-006	0	2-8362	Main Landing Gear Door Uplock Delivery Assembly- Conversion of 2-8362-4 to 2-8362-5	32-32-68	8/10/2012
2-8362-32-010	0	2-8362-50, -51	Landing Gear- Left Main Landing Gear Uplock Delivery Assembly- Conversion of 2-8362-50 to 2-8362-51	32-32-78	8/10/2012
2-8363-32-007	0	2-8363	Main Landign Gear Door Uplock Delivery Assembly- Conversion of 2-8363-4 to 2-8363-5	32-32-68	8/10/2012
2-8363-32-011	0	2-8363-50, -51	Landing Gear- Right Main Landing Gear Door Uplock Delivery Assembly- Conversion of 2-8363-50 to 2-8363-51	32-32-78	8/10/2012
2-8474-32-1	-	2-8474	Landing Gear Main Landing Gear Door Actuator Assembly	32-32-15	5/30/2014
2-8476-32-1	-	2-8476	Landing Gear MLG Retract Actuator Assembly Triumph P/N 2-8476-1 Re-application of HVOF Coating	32-32-16	1/5/2017
2-8512-32-001	-	2-8512	Landing Gear MLG Uplock Mechanism (L) Triumph P/N 2-8512-1	32-32-80	9/21/2016
2-8513-32-001	-	2-8513	Landing Gear MLG Uplock Mechanism (R) Triumph P/N 2-8513-1	32-32-80	9/21/2016

Triumph Actuation Systems - Yakima
Current Service Bulletin List

<u>Service Bulletin No.</u>	<u>Revision</u>	<u>Part No.</u>	<u>Nomenclature</u>	<u>CMM No</u>	<u>Rev Date</u>
2-8554-32-1	-	2-8554	Landing Gear MLG Side Brace Actuator Assembly Triumph P/N 2-8554-2 Split Ball Bearing Replacement	32-31-07	7/26/2017
6-0419-32-001	-	6-0419	Hydraulic Alternate Extend Power Pack	32-35-08	10/13/2015
H10411003-32-1	-	H10411003	Landing Gear Body Landing Gear Center Door Actuator Assembly	32-32-55	11/29/2012
H10415003-32-1	-	H10415003	Outer Door Actuator Assembly - Body Landing Gear, Bonding Strap Upgrade	32-32-57	5/21/2010
H10671-32-001	1	H10671003	JUN 19/13 Landing Gear- Truck Position Valve- Conversion of H10671003 to H10671004	32-32-24	7/2/2013